

# ORACLE<sup>®</sup>

TECHNOLOGY



## FORD MUSTANG FOG LIGHT HALO INSTALLATION

### TOOLS:



FLATHEAD



HEAT SOURCE



ADHESIVE

STEP #1: IN ORDER TO OPEN THE LIGHT WE WILL FIRST NEED TO HEAT THE HOUSING. IF USING A HEAT GUN BEGIN BY HEATING THE SEAL EVENLY WHILE CONSTANTLY MOVING THE HEAT GUN. IF USING AN OVEN: PREHEAT TO 215°F AND PLACE THE LIGHT IN THE OVEN FOR 10 MINUTES.



- PRE-HEAT THE OVEN TO 215°F (OR 100°C)
- CENTER LIGHT IN OVEN FOR EVEN HEATING
- SET TIMER FOR 10 MIN (GAS OR ELECTRIC)

### OPENING THE FOG LIGHT:



A) USING THE FLATHEAD SCREWDRIVER, GENTLY PRY THE LENS AROUND THE LIGHT SEAL.




B) EVENTUALLY THE LENS WILL PART WITH THE FOG HOUSING. BE GENTLE AND TAKE YOUR TIME HERE.



C) IF THE LENS DOES NOT SEPARATE RE-HEAT THE LIGHT FOR 5 MINUTES AND TRY AGAIN

### ROUTE THE WIRES:



THE WIRES CAN BE ROUTED OUT OF THE EXISTING VENT HOLE.

FOR A CLEANER LOOK YOU CAN DRILL A HOLE AT THE BOTTOM OF THE FOG LIGHT TO ROUTE THE WIRES OUT OF.

### SECURE THE RING:

REMOVE THE RING BACKING TO EXPOSE THE 3M MOUNTING ADHESIVE.



AS AN EXTRA PRECAUTION YOU CAN ADD ADDITIONAL ADHESIVE TO THE MOUNTING SURFACE OF THE RING

TO SECURE THE LENS TO THE HOUSING USE A BLACK 100% SILICONE ADHESIVE.



WE RECOMMEND GE BRAND SILICONE II THIS CAN BE FOUND AT ANY LOWES/HOME DEPOT

NOW CLAMP THE LENS TO THE HOUSING FOR THE RECOMMENDED TIME FOR THE SILICONE TO FULLY SET.

